

Temperature Conversion Table

°C	°F	°C	°F	°C	°F	°C	°F
-273	-459.4	190	+374	740	+1364	1880	+3416
-260	-436	200	+392	750	+1382	1900	+3452
-240	-400	204	+400	760	+1400	1920	+3488
-220	-364	210	+410	780	+1436	1940	+3524
-200	-328	220	+428	800	+1472	1960	+3560
-180	-292	230	+446	820	+1508	1980	+3596
-160	-256	232	+450	840	+1544	2000	+3632
-140	-220	240	+464	860	+1580	2020	+3668
-120	-184	250	+482	880	+1616	2040	+3704
-100	-148	260	+500	900	+1652	2060	+3740
-90	-130	270	+518	920	+1688	2080	+3776
-80	-112	280	+536	940	+1724	2100	+3812
-70	-94	290	+554	960	+1760	2120	+3848
-57	-70	300	+572	980	+1796	2140	+3884
-55	-67	310	+590	1000	+1832	2160	+3920
-54	-65	316	+600	1020	+1868	2180	+3956
-40	-40	320	+608	1040	+1904	2200	+3992
-34	-30	330	+626	1060	+1940	2220	+4028
-30	-22	340	+644	1080	+1976	2240	+4064
-29	-20	350	+662	1100	+2012	2260	+4100
-20	-4	360	+680	1120	+2048	2280	+4136
-10	+14	370	+698	1140	+2084	2300	+4172
0	+32	380	+716	1160	+2120	2320	+4208
1	+33.8	390	+734	1180	+2156	2340	+4244
5	+41.0	400	+752	1200	+2192	2360	+4280
10	+50.0	410	+770	1220	+2228	2380	+4316
15	+59.0	420	+788	1240	+2264	2400	+4352
20	+68.0	430	+806	1260	+2300	2420	+4388
23	+73.4	440	+824	1280	+2336	2440	+4424
25	+77.0	450	+842	1300	+2372	2460	+4460
30	+86.0	460	+860	1320	+2408	2480	+4496
35	+95.0	470	+878	1340	+2444	2500	+4532
40	+104.0	480	+896	1360	+2480	2520	+4568
45	+113.0	490	+914	1380	+2516	2540	+4604
50	+122.0	500	+932	1400	+2552	2560	+4640
55	+131.0	510	+950	1420	+2588	2580	+4676
60	+140.0	520	+968	1440	+2624	2600	+4712
65	+149.0	530	+986	1460	+2660	2620	+4748
70	+158.0	540	+1004	1480	+2696	2640	+4784
75	+167.0	550	+1022	1500	+2732	2660	+4820
80	+176.0	560	+1040	1520	+2768	2680	+4856
82	+180.0	570	+1058	1540	+2804	2700	+4892
85	+185.0	580	+1076	1560	+2840	2720	+4928
90	+194.0	590	+1094	1580	+2876	2740	+4964
95	+203.0	600	+1112	1600	+2912	2760	+5000
100	+212.0	610	+1130	1620	+2948	2780	+5036
107	+225.0	620	+1148	1640	+2984	2800	+5072
110	+230.0	630	+1166	1660	+3020	2820	+5108
120	+248.0	640	+1184	1680	+3056	2840	+5144
121	+250.0	650	+1202	1700	+3092	2860	+5180
130	+266.0	660	+1220	1720	+3128	2880	+5216
135	+275.0	670	+1238	1740	+3164	2900	+5252
140	+284.0	680	+1256	1760	+3200	2920	+5288
149	+300.0	690	+1274	1780	+3236	2940	+5324
150	+302.0	700	+1292	1800	+3272	2960	+5360
160	+320.0	710	+1310	1820	+3308	2980	+5396
170	+338.0	720	+1328	1840	+3344	3000	+5432
180	+356	730	+1346	1860	+3380		



1-800-576-SEAL